



Photographs of Gobernador Creek, Study Reach CC-3 (See Figure 1-2 for location). Notice that bedrock sections and medium to large boulders dominate the stream channel. There are also deposits and bars consisting of small boulders, cobble, gravel, and sand. There are alternating sections of riffles and pools. The pool shown in the photograph to the far right is approximately 30 feet in diameter and 6 feet deep. The riparian vegetation is dense, and consists mostly of native species. Dominant riparian trees include white alder, western sycamore, coast live oak, and arroyo willow.

